



**APPENDIX 3: Photographs of test setup**

**Conducted Emission**



**Photo 1**




**Photo 2**

### Radiated Spurious Emission



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**

**Head Office EMC Lab.**


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999


Facsimile : +81 596 24 8124

**Worst Case Position**  
**(Module/Antenna Horizontal: X-axis/Z-axis, Vertical: X-axis/Y-axis)**


**<Antenna>**  
**X-axis**




**Y-axis**




**Z-axis**




**<Module>**  
**X-axis**



**Y-axis**



**Z-axis**



**End of Report**