

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

Radiated Spurious Emission




Photo 1




Photo 2

Worst Case Position
(11b Horizontal: Z-axis/ Vertical:X-axis)
(11n20/11n40 Horizontal: X-axis/ Vertical:Z-axis)


X-axis



Y-axis



Z-axis



End of Report