

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999


Facsimile : +81 596 24 8124

Worst Case Position
(Antenna: Horizontal: X0-axis / Vertical: X90-axis)


X0-axis




X90-axis




Y0-axis




Y90-axis



Z0-axis




Z90-axis




Worst Case Position
(Module: Horizontal: X-axis / Vertical: X-axis)

X-axis



Y-axis



Z-axis



End of Report