



**APPENDIX 3: Photographs of test setup**

**Radiated Spurious Emission**



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124


**Worst Case Position**

Below 1GHz (Hori: Antenna X, Module X / Vert: Antenna X, Module X)


Above 1GHz (Hori: Antenna X, Module X / Vert: Antenna Y, Module X)

**Antenna**


**X-axis**



**Y-axis**




**Z-axis**




**Module**


**X-axis**



**Y-axis**



**Z-axis**



**End of Report**