










Report No.: EED32L00366301

PHOTOGRAPHS OF TEST SETUP





Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-1(Below 1GHz)













Report No. : EED32L00366301 Page 55 of 61



Radiated spurious emission Test Setup-2(Above 1GHz)



Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.









