


Report No.: EED32N80606101 Page 17 of 28

8 PHOTOGRAPHS OF TEST SETUP

Test model No.: 1371930



Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-1(Below 1GHz)



Report No.: EED32N80606101 Page 18 of 28



Radiated spurious emission Test Setup-2(Above 1GHz)



Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.









