

Appendix 1



TÜV Rheinland Group

www.tuv.com

Prüfbericht - Nr.:
Test Report No.


14006777 002

Seite 1 von 1
Page 1 of 1



1 PK
MAXH

Ref 87 dBμV Att 10 dB *RBW 3 kHz Delta 3 [T1] -51.27 dB
*VBW 1 MHz SWT 40 ms 134.40000000 kHz



Date: 4.OCT.2004 16:44:08