



**APPENDIX 3: Photographs of test setup**

**Radiated Emission**




**Photo 1**



**Photo 2**

**Worst Case Position**


**ECU**  
Below 30MHz  
X-axis  
Above 30MHz  
Horizontal: X-axis / Vertical: X-axis  
X-axis




**Y-axis**




**Z-axis**




**Room Antenna**  
Below 30MHz  
X-axis  
Above 30MHz  
Horizontal: X-axis / Vertical: X-axis  
X-axis



**Y-axis**




**Z-axis**




**Worst Case Position**


**Door Antenna**  
Below 30MHz  
X-axis  
Above 30MHz  
Horizontal: X-axis / Vertical: X-axis  
X-axis




**Y-axis**



**Z-axis**




**Trunk Antenna**  
Below 30MHz  
X-axis  
Above 30MHz  
Horizontal: X-axis / Vertical: X-axis  
X-axis



**Y-axis**



**Z-axis**



**End of Report**