
Appendix C

Date: 2009-11-23


Test report no.: 60.870.9.017.01F Model no.: AWD204 (Receiver)


Photos of EUT – Internal EUT Photos






Page 1 of 7
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Shatin, Hong Kong.





Page 2 of 7
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Shatin, Hong Kong.







Page 3 of 7
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Shatin, Hong Kong.







Page 4 of 7
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Shatin, Hong Kong.





Page 5 of 7
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Shatin, Hong Kong.





Page 6 of 7
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Shatin, Hong Kong.

