

Photo Report on Test Setups

In Vehicle Infotainment

SMART CRONY IVI

FCC ID: NT8-SMARTCRONYIVI

Test Report Reference: MDE_VIS_1916_FCC_Photo_Report

Test Laboratory:

7layers GmbH
Borsigstrasse 11
40880 Ratingen
Germany



Deutsche
Akkreditierungsstelle
D-PL-12140-01-01
D-PL-12140-01-02
D-PL-12140-01-03

Note:

The following test results relate only to the devices specified in this document. This report shall not be reproduced in parts without the written approval of the test laboratory.

7layers GmbH

Borsigstraße 11
40880 Ratingen, Germany
T +49 (0) 2102 749 0
F +49 (0) 2102 749 350

Geschäftsführer/
Managing Directors:
Frank Spiller
Bernhard Retka
Alexandre Norré-Oudard

Registergericht/registered:
Düsseldorf HRB 75554
USt-Id.-Nr./VAT-No. DE203159652
Steuer-Nr./TAX-No. 147/5869/0385

a Bureau Veritas
Group Company

www.7layers.com



Photo 1: Test setup for radiated measurements (9 kHz - 30 MHz)




Photo 2: Test setup for radiated measurements (30 MHz - 1 GHz)



Photo 3: Test setup for radiated measurements (1 GHz – 26 GHz)




Photo 4: Test setup for radiated measurements (26 GHz - 40 GHz)



Photo 5: Test setup for conducted measurements