

May 28, 2002

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
USA

Subject: FCC ID: NTAXMETER2 - clarifications

Gentlemen,

Following your request we provide additional clarification regarding Low Power Transceiver NTAXMETER2:

The actual installation of the unit is always inside and at the bottom of the metal pit buried in the ground with unlimited width, so the test configuration is absolutely the worst-case scenario compared to the actual installation.

Sincerely yours



Roman Sternberg
VP Marketing