1. PHOTOGRAPHS OF MEASUREMENT

1.1. Photos of Conducted Disturbance Measurement



Front View of Conducted Disturbance Measurement




Side View of Conducted Disturbance Measurement



1.2. Radiated Disturbance Measurement

Below 1GHz

Above 1GHz



Audix Technology (Wujiang) Co., Ltd. EMC Dept. Report No.: ACWE-F1306002A

1.3. Measurement for section 6/7/8/9/10

