


6. Photographs of the Test Setup

Photograph 1: Set-up for Conducted Emissions at Antenna Port




Prüfbericht - Nr.: 12701745 001
Test Report No.:

Seite 118 von 124
Page 118 of 124

Photograph 2: Set-up for AC Power Line Conducted Emission of Transmitter, Front View




Photograph 3: Set-up for AC Power Line Conducted Emission of Transmitter, Rear View



Prüfbericht - Nr.: 12701745 001
Test Report No.:

Seite 119 von 124
Page 119 of 124

Photograph 4: Set-up for Radiated Emission of Transmitter, Front View



Photograph 5: Set-up for Radiated Emission of Transmitter, Rear View

