





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


APPENDIX I: INTERNAL PHOTOGRAPHS



PHOTOGRAPH 6: BOTTOM OF MAIN PCB




PHOTOGRAPH 7: TOP OF MAIN PCB



PHOTOGRAPH 8: TOP OF RF PCB WITH SHIELDS



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 9: TOP OF RF PCB WITH SHIELDS REMOVED



PHOTOGRAPH 10: BOTTOM OF RF PCB WITH SHIELDS



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 11: BOTTOM OF RF PCB WITH SHIELDS REMOVED



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 12: TOP OF PCB'S IN CHASSIS



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 13: BOTTOM OF INSIDE COVER




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 14: INSIDE OF TOP COVER



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 15: INSIDE OF ANTENNA