




Photos for E2-455 Licensed Radio


Photos_E2-455_V1-3

Internal Photos

Under Side View



Under Side View – Heat Sink removed




E2-455 User Manual

Top Side View




Top Side – Shields Removed (C1, C3, C4, C5)



E2-455 User Manual

Top Side – C92 Shields Removed



Label Location



REVISION HISTORY

Issue No.	Date	Details of Amendment
1.0	05/02/2018	Initial Issue – From E2-455 User Manual
1.1	03/03/2018	Updated Top Side with Small Shield removed.
1.2	23/03/2018	Added Photo with Heat-Sink removed. Updated Label Location with IC/ISED HVIN labelling.
1.3	19/01/2022	Added Photo for C92. ELPRO updates.