




## APPENDIX II

### PHOTOGRAPHS OF TEST SETUP

#### CONDUCTED EMISSION SETUP PHOTO






**Compliance Certification Services Inc.**

Report No.: 90728208-RP1

FCC ID: OL3OT8082

Date of Issue: October 13, 2010

## RADIATED EMISSION SETUP PHOTOS





## POWERLINE CONDUCTED EMISSIONS SETUP PHOTOS

