


Prüfbericht - Nr.: 16007560 001
Test Report No.:

Seite 13 von 15
Page 13 of 15

6 Photographs of the Test Set-Up

Photograph 1: Set-up for Radiation Measurement Below 30MHz



Prüfbericht - Nr.: 16007560 001
Test Report No.:

Seite 14 von 15
Page 14 of 15

Photograph 2: Set-up for Radiation Measurement below 1GHz

