

Prüfbericht - Nr.: 16002983 001


Test Report No.:

Seite 13 von 15

Page 13 of 15

6 Photographs of the Test Set-Up

Photograph 1: Set-up for Radiation Measurement Below 30MHz



Prüfbericht - Nr.: 16002983 001

Test Report No.:

Seite 14 von 15

Page 14 of 15

Photograph 2: Set-up for Radiation Measurement below 1GHz

