

Federal Communication Commission  
Equipment Authorization Branch  
7435 Oakland Mills Road  
Columbia, MD 21046

April 30, 2002

Re: Internal Photo Updated  
Applicant: Kyocera Wireless Corp.  
FCC ID: OVFKWC-2345  
731 Confirmation Number: EA443383

The pillow gasket on the backside of the front housing was fall out while the internal photos were taken. A few of related pictures have been re-taken and the internal photo package has been updated. The updated internal photo package, re-named "Exhibit 19 \_ Internal Photos Updated" has been uploaded to FCC OET web site via the path - Add Attachments, under FCC ID OVFKWC-2345. This letter is to inform the update.

Best Regards,

Lin Lu

Regulatory Engineer, Senior Staff

Tel: (858) 882-2406  
Email: LLu@qcpi.com