

|                        |   |   |          |
|------------------------|---|---|----------|
| <i>Nemko USA, Inc.</i> |   | 11696 Sorrento Valley Road, Suite F, San Diego, CA 92121<br>Phone (858) 755-5525 Fax (858) 452-1810 |          |
| DATE                   | DOCUMENT NAME                               | DOCUMENT #  | PAGE     |
| May 9, 2006            | Kyocera Wireless Corp. K323 FCC Test Report | 2006 050299 K323 PART 15.247  | 25 of 31 |

### Photograph 3. Conducted Emissions Test Configuration

TXTVL10079 Charger



TXTVL10080 Charger



|                        |   |   |             |
|------------------------|---|---|-------------|
| <b>Nemko USA, Inc.</b> |   | 11696 Sorrento Valley Road, Suite F, San Diego, CA 92121<br>Phone (858) 755-5525 Fax (858) 452-1810 |             |
| <b>DATE</b>            | <b>DOCUMENT NAME</b>                        | <b>DOCUMENT #</b>   | <b>PAGE</b> |
| May 9, 2006            | Kyocera Wireless Corp. K323 FCC Test Report | 2006 050299 K323 PART 15.247  | 26 of 31    |

### Photograph 4. Radiated Emissions Test Configuration

TXTVTL10079 Charger



TXTVTL10080 Charger



|                        |   |   |          |
|------------------------|---|---|----------|
| <i>Nemko USA, Inc.</i> |   | 11696 Sorrento Valley Road, Suite F, San Diego, CA 92121<br>Phone (858) 755-5525 Fax (858) 452-1810 |          |
| DATE                   | DOCUMENT NAME                               | DOCUMENT #  | PAGE     |
| May 9, 2006            | Kyocera Wireless Corp. K323 FCC Test Report | 2006 050299 K323 PART 15.247  | 27 of 31 |

### Photograph 5. Fundamental and Spurious Emissions Test Configuration

