


Appendix P: Internal Photographs




Photograph 12: Front Cover Removed




Photograph 13: Back without Battery Installed




Photograph 14: IF Board View 1




Photograph 15: IF Board View 2




Photograph 16: IF Board View 3




Photograph 17: IF Board View 4




Photograph 18: IF Board View 5




Photograph 19: IF Board View 6




Photograph 20: Main Board View 1




Photograph 21: Main Board View 2




Photograph 22: Main Board View 3



Photograph 23: Main Board Back View 1



Photograph 24: Main Board Back View 2



Photograph 25: Main Board Back View 3



Photograph 26: Radio Shield