



## **APPENDIX D – DUT PHOTOS**

**Figure** 

D1

## XL-200P C1D1 Radio












Top Bottom w/o Antenna


















45461391 R2.1

11 July 2017



Figure: D3

# **Accessory Photo**

**Part Number** 

# 14034-4045-01 Li\_lon Battery Pack

## **Front View**



## **Back View w/o Metal Shim**




Back View w/ Metal Shim



**Side View** 





45461391 R2.1

11 July 2017



Figure: D4

# **Accessory Photo**

**Part Number** 

# 14034-4010-01 Li\_lon Battery Pack

## **Front View**



## **Back View**









Figure: D5

# **Accessory Photo**


**Part Number** 

# 12082-0600-01 Standard Speaker Microphone
















Celltech
Testing and Engineering Services Lab

Figure

D10

# KRY 101 1609/1 Leather Belt Loop w/ 12082-3230-01 D-Swivel

## Front



#### **Back**



#### Side





Test Report S/N: Test Report Issue Date:

45461391 R2.1 11 July 2017

