

7 Annex D: INTERNAL PHOTOGRAPHS OF THE EQUIPMENT

Photo 1:

SBC HC8522/37, SBC HC8542/37, SBC HC8582/37




Photo 2:

SBC HC8522/37, SBC HC8542/37, SBC HC8582/37




Photo 3:

SBC HC8522/37, SBC HC8542/37, SBC HC8582/37




Photo 4:
SBC HC8525/37




Photo 5:
SBC HC8525/37





Photo 7:

SBC HC8525/37 ; SBC HC8545/37 ; SBC HC8585/37






Photo 9:

SBC HC8525/37 ; SBC HC8545/37 ; SBC HC8585/37




Photo 10:
SBC HC8545/37




Photo 11:
SBC HC8545/37




Photo 12:
SBC HC8545/37




Photo 13:
SBC HC8585/37




Photo 14:
SBC HC8585/37



Photo 15:
SBC HC8585/37

