
Photos Taken During Radiated Emission Testing

View of the <u>Radiated Emission</u> Testing in the 3 Meter Chamber



View of the EUT on the 10 Meter Site, during the <u>Radiated Emission</u> Testing.



L.S. Compliance, Inc.
Test Report Number: 301378

Prepared For: Biocentric Solutions, Inc.