Report No. :FA0O0714-06

## Appendix D. SAR Test Setup Photos

## **Head Exposure Condition**





Right Cheek at 0mm

Right Tilted at 0mm







Left Tilted at 0mm

TEL: 886-3-327-3456 Page: D1 of D3 FAX: 886-3-328-4978 Issued Date: Jul. 19, 2022

Template version: 211220





Front at 10 mm

Back at 10 mm




Right Side at 10 mm



Left Side at 10 mm



Top Side at 10 mm



Bottom Side at 10 mm

TEL: 886-3-327-3456 Page: D2 of D3
FAX: 886-3-328-4978 Issued Date: Jul. 19, 2022

Template version: 211220



## SPORTON LAB. FCC SAR TEST REPORT Report No. :FA0O0714-06



Front at 10 mm

Back at 10 mm



Left Side at 0 mm

TEL: 886-3-327-3456 Page: D3 of D3 FAX: 886-3-328-4978 Issued Date: Jul. 19, 2022

Template version: 211220