


Len Gordon
Report Number 000921 123
Lennovator, Base Unit
Test Setup Photographs

Conducted Emission Test, Front View



Conducted Emission Test, Side View



Radiated Emission Test Setup, Rear View



Radiated Emission Test Setup, Side View



Radiated Emission Test Setup, Front View

