


Client:	Xetawave LLC	Job Number:	JD103500
Model:	Xeta1	T-Log Number:	T103571
		Project Manager:	Christine Krebill
Contact:	Sandee Malang	Project Coordinator:	-
Standard:	FCC Part 90, RSS-119	Class:	N/A

Test Configuration Photographs (Radiated Emissions)



Client: Xetawave LLC	Job Number: JD103500
Model: Xeta1	T-Log Number: T103571
	Project Manager: Christine Krebill
Contact: Sandee Malang	Project Coordinator: -
Standard: FCC Part 90, RSS-119	Class: N/A

Test Configuration Photographs (Radiated Emissions)



Client:	Xetawave LLC	Job Number:	JD103500
Model:	Xeta1	T-Log Number:	T103571
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 90, RSS-119	Project Coordinator:	-
		Class:	N/A


Test Configuration Photographs (Radiated Emissions)





Client:	Xetawave LLC	Job Number:	JD103500
Model:	Xeta1	T-Log Number:	T103571
		Project Manager:	Christine Krebill
Contact:	Sandee Malang	Project Coordinator:	-
Standard:	FCC Part 90, RSS-119	Class:	N/A

Test Configuration Photographs (Radiated Emissions - EUT Flat)




Client: Xetawave LLC	Job Number: JD103500
Model: Xeta1	T-Log Number: T103571
	Project Manager: Christine Krebill
Contact: Sandee Malang	Project Coordinator: -
Standard: FCC Part 90, RSS-119	Class: N/A

Test Configuration Photographs (Radiated Emissions - EUT Side)



Client:	Xetawave LLC	Job Number:	JD103500
Model:	Xeta1	T-Log Number:	T103571
		Project Manager:	Christine Krebill
Contact:	Sandee Malang	Project Coordinator:	-
Standard:	FCC Part 90, RSS-119	Class:	N/A


Test Configuration Photographs (Radiated Emissions - EUT Upright)






Client: Xetawave LLC	Job Number: JD103500
Model: Xeta1	T-Log Number: T103571
	Project Manager: Christine Krebill
Contact: Sandee Malang	Project Coordinator: -
Standard: FCC Part 90, RSS-119	Class: N/A

### Test Configuration Photographs (RF conducted measurements)



Client: Xetawave LLC	Job Number: JD103500
Model: Xeta1	T-Log Number: T103571
	Project Manager: Christine Krebill
Contact: Sandee Malang	Project Coordinator: -
Standard: FCC Part 90, RSS-119	Class: N/A

Test Configuration Photographs (RF conducted measurements)






Client: Xetawave LLC	Job Number: JD103500
Model: Xeta1	T-Log Number: T103571
	Project Manager: Christine Krebill
Contact: Sandee Malang	Project Coordinator: -
Standard: FCC Part 90, RSS-119	Class: N/A

### Test Configuration Photographs (RF conducted measurement - Frequency Stability)



Client:	Xetawave LLC	Job Number:	JD103500
Model:	Xeta1	T-Log Number:	T103571
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 90, RSS-119	Project Coordinator:	-
		Class:	N/A

### Test Configuration Photographs (RF conducted measurement - Transient Frequency Behavior)



Client: Xetawave LLC	Job Number: JD103500
Model: Xeta1	T-Log Number: T103571
	Project Manager: Christine Krebill
Contact: Sandee Malang	Project Coordinator: -
Standard: FCC Part 90, RSS-119	Class: N/A

Test Configuration Photographs (RF conducted measurement - Transient Frequency Behavior)

