


2.11 – Photos taken during testing



View of the AP100BS, on the pedestal, during the Radiated Emissions tests.



View of the AP100BS, on the table, during the Conducted Emissions tests.