



SETUP PHOTOGRAPHS

This document contains 10 photographs


Photograph No.1
Conducted spurious emissions measurement setup



Photograph No.2
Radiated emissions measurement setup in the anechoic chamber with loop antenna



Photograph No.3
Radiated emissions measurement setup in the anechoic chamber
with biconilog antenna



Photograph No.4
Radiated emissions measurement setup in the anechoic chamber with double ridged guide antenna




Photograph No.5
Radiated emissions measurement setup at the OATS with double ridged guide antenna



Photograph No.6
Unintentional radiated emissions measurement setup in the anechoic chamber with biconilog antenna



Photograph No.7
Unintentional radiated emissions measurement setup in the anechoic chamber with double ridged guide antenna



Photograph No.8
Unintentional radiated emissions measurement, EUT configuration



Photograph No.9
Conducted emissions measurement setup



Photograph No.10
Conducted emissions measurement setup

