

29 January 2010

Reason for Exhibit Supersede - PKTNODEBAFB

The following exhibits were superseded due to an incorrect safe operating distance having been stated for the equipment. The incorrect stated distance was 2.83 metres which has now been corrected to 4.06 metres in accordance with the updated MPE calculation.

Exhibits superseded:

MPE Calculation

Installation Guide

These superseded exhibits were available to view in the grant listing for less than half a day.

RFI Global Services TCB

I Lellan