



**APPENDIX 3: Photographs of test setup**

**Radiated Spurious Emission**



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124


**Worst Case Position**

(Above 1GHz:Horizontal: X-3-axis / Vertical:X-1-axis)  
(Below 1GHz:Horizontal: Y-2-axis / Vertical:Y-2-axis)


**X-1-axis**




**Y-1-axis**




**X-2-axis**




**Y-2-axis**



**X-3-axis**




**Y-3-axis**




### Worst Case Position


**Z-1-axis**



**Z-2-axis**



**Z-3-axis**



**End of Report**