



PHOTOS - TEST SETUP


Company: Radwin

Product Name: AP0168031


Report No.: RDWN78 – Test Setup Photos

1. Test Setup Photographs


1.1.1. Test Setup - RE#1 - Radiated Emissions - 3m Chamber




Spurious Emissions RW-9061-5006



Spurious Emissions RW-9105-5158




Spurious Emissions RW-9401-5004



Spurious Emissions RW-9402-5001

1.1.2. Test Setup - RF#2 - Conducted



Conducted RF



575 Boulder Court
Pleasanton, California 94566, USA
Tel: +1 (925) 462 0304
Fax: +1 (925) 462 0306
www.micomlabs.com