




6. PHOTOS OF TESTING

- Conducted Emission test





Spectrum Research & Testing Lab., Inc.
No. 101-10, Ling 8,
Shan-Tong Li, Chung-Li
City, Taoyuan, Taiwan

TEST REPORT

Reference No.: A08030603
Report No.: FCCA08030603
FCC ID: Q7Z-GT200R1
Page:60 of 63
Date: Mar. 17, 2008

- Radiated test (TX)



Lab Code: 200099-0
FMNG-059.10 REPORT



Spectrum Research & Testing Lab., Inc.
No. 101-10, Ling 8,
Shan-Tong Li, Chung-Li
City, Taoyuan, Taiwan

TEST REPORT

Reference No.: A08030603
Report No.: FCCA08030603
FCC ID: Q7Z-GT200R1
Page:61 of 63
Date: Mar. 17, 2008

- Radiated test (Link&Standby)



Lab Code: 200099-0
FMNG-059.10 REPORT



- Radiated test (Charge)

