



**Spectrum Research & Testing Lab., Inc.**  
No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li,  
Chung-Li City, Taoyuan County 320, Taiwan (R.O.C.)

## PHOTOS OF TESTING

- Radiated test (below 30M, TX & Standby)





**Spectrum Research & Testing Lab., Inc.**  
No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li,  
Chung-Li City, Taoyuan County 320, Taiwan (R.O.C.)

- Radiated test (below 30M, Link)





**Spectrum Research & Testing Lab., Inc.**  
No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li,  
Chung-Li City, Taoyuan County 320, Taiwan (R.O.C.)

- Radiated test (below 1G, TX & Standby)







**Spectrum Research & Testing Lab., Inc.**  
No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li,  
Chung-Li City, Taoyuan County 320, Taiwan (R.O.C.)

- Radiated test (below 1G, Link)





**Spectrum Research & Testing Lab., Inc.**  
No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li,  
Chung-Li City, Taoyuan County 320, Taiwan (R.O.C.)

- Radiated test (above 1G, TX & Standby)





**Spectrum Research & Testing Lab., Inc.**  
No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li,  
Chung-Li City, Taoyuan County 320, Taiwan (R.O.C.)

- Radiated test (above 1G, Link)

