


Report No.: E-F1703013

Rev: 00

8 Photographs

8.1 Radiated Emission Test Setup

Below 1G



Above 1G



Dongguan Yaxu (AiT) Technology Limited No. 22, Jinqianling Third Street, Jitigang, Huangjiang, Dongguan, Guangdong, China.



Rev: 00

8.2 Conducted Emissions Test Setup

