


7. Photographs of the Test Set-Up


Photograph 1: Set-up for Spurious Emissions (Front View)




Prüfbericht - Nr.: 10052091 001
Test Report No.

Seite 33 von 36
Page 33 of 36

Photograph 2: Set-up for Spurious Emissions (Back View 1)



Photograph 3: Set-up for Spurious Emissions (Back View 2)



Prüfbericht - Nr.: 10052091 001
Test Report No.

Seite 34 von 36
Page 34 of 36

Photograph 4: Set-up for Conducted testing



Photograph 5: Set-up for for Mains Conducted testing Back



Prüfbericht - Nr.: 10052091 001
Test Report No.

Seite 35 von 36
Page 35 of 36

Photograph 6: Set-up for Mains Conducted testing Front

