


## **Test Configuration Photographs**

The conducted emission photograph was not available due to a problem with the camera. The test setup was identical to the radiated emission test except for the use of a metal ground plane 40 cm from the rear the unit and an AMN located 1 meter from the power supply.



close-up of EUT with antenna horizontal

**October 20, 2004 with Shield in place**

