





Report No.: 2108C136



AC Power Line Conducted Emissions Test Photos








Radiated Emissions Test Photos

9 kHz to 30 MHz








Radiated Emissions Test Photos

30 MHz to 1000 MHz








Radiated Emissions Test Photos

Above 1 GHz







RALN 5GHZ DFS Test Photos

