

**FIGURE 1:** PLI Photograph Number 5392C3333SJ-02 illustrates the rear view of the Equipment Under Test in Radiated Electromagnetic Interference Test Configuration #1.



**FIGURE 2:** PLI Photograph Number 5392C3333SJ-04 the rear view of the Equipment Under Test in Conducted Electromagnetic Interference Test Configuration #1.

