

APPENDIX 3: Photographs of Test Setup

Conducted Emission




Photo 1




Photo 2

Radiated Spurious Emission




Photo 1





Photo 2

Worst Case Position

Test Range	Horizontal	Vertical
Below 1 GHz	X-axis	X-axis
Above 1 GHz	Y-axis	Z-axis


X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests




Photo 1



Photo 2

End of Report