

APPENDIX 4: Photographs of test setup

Photographs of Relay unit

Photograph A1: Front



Photograph A4: Rear



Photograph A2: Left



Photograph A5: Right



Photograph A3: Top




Photograph A6: Bottom




Photograph A7: EUT




Photograph A8: EUT is mounted on Relay unit (Cover removed)




Photograph A9: Measurement with AC adapter connected at customer's request



Antenna position



Photographs of setup

Photograph B1: Body, Front, 0 mm (Front view)	Photograph B3: Body, Right, 0 mm (Front view)
	
Photograph B2: Body, Front, 0 mm (Side view)	Photograph B4: Body, Right, 0 mm (Side view)
	

Photograph B5: Body, Bottom tilt, 0 mm
(Front view)



Photograph B6: Body, Bottom tilt, 0 mm
(Side view)



End of Report