

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1



Photo 2

Radiated Spurious Emission



Photo 1




Photo 2

Worst Case Position


Below 30 MHz (X-axis)

Above 30 MHz (Horizontal: X-axis / Vertical: X-axis)


X-axis




Y-axis



Z-axis



Worst case position



Without Actuator (worst)



With Actuator

End of Report