

ANNEX C


PHOTOGRAPHS (Number of photographs: 7)

Report No.: 26826RET

Report No.:	
26826RET	Page: 1 of 8
Date: 2007-11-23	Annex C




1. Equipment (front view)




Report No.: 26826RET	Page: 2 of 8
Date: 2007-11-23	Annex C




2. Equipment (back view)



Report No.: 26826RET	Page: 3 of 8
Date: 2007-11-23	Annex C








Report No.: 26826RET	Page: 4 of 8
Date: 2007-11-23	Annex C




4. General test set-up for radiated measurements.



Report No.: 26826RET	Page: 5 of 8
Date: 2007-11-23	Annex C




5. Test set-up for radiated measurements below 1 GHz.




Report No.: 26826RET	Page: 6 of 8
Date: 2007-11-23	Annex C



6. Test set-up for radiated measurements above 1 GHz.



Report No.: 26826RET	Page: 7 of 8
Date: 2007-11-23	Annex C







Report No.: 26826RET	Page: 8 of 8
Date: 2007-11-23	Annex C