SETUP PHOTOGRAPHS
This document contains 5 photographs
This document contains a photographs

Photograph No.1
Spurious radiated emissions and occupied bandwidth measurement setup in the anechoic chamber




Photograph No.2 Radiated emissions measurement setup in the anechoic chamber, close view



Photograph No.3
Unintentional radiated emissions measurement setup in the anechoic chamber



Photograph No.4 Unintentional radiated emissions measurement setup, close view



Photograph No.5 Conducted emissions measurement setup

