


Internal Photographs



Photo of ODU showing services compartment with rear cover removed

8/10/2015

Internal Photographs



Internal photo of ODU with service compartment removed from modem board

8/10/2015

Internal Photographs




Photo of modem board - top view

8/10/2015

Internal Photographs




Photo of modem board - bottom view

8/10/2015

Internal Photographs




Photo of interface board - top view

Internal Photographs



Photo of interface board - bottom view

8/10/2015

Internal Photographs




Photo of RF module - top view

Internal Photographs



Photo of RF module - bottom view