Rhein Tech Laboratories, Inc. 360 Herndon Parkway Suite 1400 Herndon, VA 20170 <u>http://www.rheintech.com</u> Client: TMI-USA, Inc. Model #: NVQRADIOZIGB1 Standards: FCC 15.247/IC RSS-210 ID's: RMK-NVQZIGB1/10839A-NVQZIGB1 Report #: 2013010

Appendix N: Internal Photographs Á Ú∣^æ^Á^-^¦Á{ Á@Á{ ∥[ ¸ ậ \* Á æ\* ^• ÈÁ




Figure 1: Memory Board Top View




Figure 2: Memory Board Bottom View




Figure 3: Radio Board Top View




Figure 4: Radio Board Bottom View




Figure 5: Battery Board Top View




Figure 6: Battery Board Bottom View




Figure 7: Final Assembly of the Circuit Boards in Data Logger with Battery Case Removed