

Photographs module 20093484PMT

Test set up

Photograph 1: - radiated emissions test, picture 1	2
PHOTOGRAPH 2: - RADIATED EMISSIONS TEST, PICTURE 2	
PHOTOGRAPH 3: - RADIATED EMISSIONS TEST, PICTURE 3	
PHOTOGRAPH 4: - CONDUCTED EMISSIONS TEST	
PHOTOGRAPH 5: - RADIATED IMMUNITY TEST, PICTURE 1	
PHOTOGRAPH 6: - RADIATED IMMUNITY TEST, PICTURE 2	7
PHOTOGRAPH 7: - RADIATED IMMUNITY TEST, PICTURE 3	
PHOTOGRAPH 8: - WATER INGRESS TEST	
PHOTOGRAPH 9 IMMERSION TEST	10



Page: 2 of 10 Report number: 20093484PMT

Photograph 1: - radiated emissions test, picture 1



Page: 3 of 10 Report number: 20093484PMT

Photograph 2: - radiated emissions test, picture 2





Page: 4 of 10 Report number: 20093484PMT


Photograph 3: - radiated emissions test, picture 3





Page: 5 of 10 Report number: 20093484PMT


Photograph 4: - conducted emissions test





Page: 6 of 10 Report number: 20093484PMT

Photograph 5: - radiated immunity test, picture 1



Page: 7 of 10 Report number: 20093484PMT

Photograph 6: - radiated immunity test, picture 2



Page: 8 of 10 Report number: 20093484PMT

Photograph 7: - radiated immunity test, picture 3





Page: 9 of 10 Report number: 20093484PMT

Photograph 8: - water ingress test





Page: 10 of 10 Report number: 20093484PMT

Photograph 9: - immersion test

