

1.0 TEST SETUP PHOTOGRAPHS



Figure 1-1. SureConnect with FM Antenna Set-up – Test Configuration #7



Figure 1-2. SureConnect with FM Antenna Set-up – Test Configuration #7



<p>FCC ID: RS2SPRCI</p>		<p>FCC Pt. 15.239 / IC RSS-210 MEASUREMENT REPORT (CERTIFICATION)</p>		<p>Reviewed by: Quality Manager</p>
<p>Test Report S/N: 0809261430.RS2</p>	<p>Test Dates: October 1-14, 2008</p>	<p>EUT Type: Satellite Radio Receiver with FM Transmitter</p>	<p>Page 1 of 8</p>	



Figure 1-3. SureConnect with FM Antenna Set-up – Test Configuration #7



Figure 1-4. SureConnect with Glass Antenna Set-up – Test Configuration #8



FCC ID: RS2SPRCI		FCC Pt. 15.239 / IC RSS-210 MEASUREMENT REPORT (CERTIFICATION)		Reviewed by: Quality Manager
Test Report S/N: 0809261430.RS2	Test Dates: October 1-14, 2008	EUT Type: Satellite Radio Receiver with FM Transmitter	Page 2 of 8	



Figure 1-5. SureConnect with Glass Antenna Set-up – Test Configuration #8



Figure 1-6. SureConnect with Glass Antenna Set-up – Test Configuration #8



FCC ID: RS2SPRCI		FCC Pt. 15.239 / IC RSS-210 MEASUREMENT REPORT (CERTIFICATION)		Reviewed by: Quality Manager
Test Report S/N: 0809261430.RS2	Test Dates: October 1-14, 2008	EUT Type: Satellite Radio Receiver with FM Transmitter	Page 3 of 8	



Figure 1-7. In-Situ with Lincoln Navigator – Test Configuration #9



Figure 1-8. In-Situ with Lincoln Navigator – Test Configuration #9


<p>FCC ID: RS2SPRCI</p>		<p>FCC Pt. 15.239 / IC RSS-210 MEASUREMENT REPORT (CERTIFICATION)</p>	<p>Reviewed by: Quality Manager</p>
<p>Test Report S/N: 0809261430.RS2</p>	<p>Test Dates: October 1-14, 2008</p>	<p>EUT Type: Satellite Radio Receiver with FM Transmitter</p>	<p>Page 4 of 8</p>



Figure 1-9. In-Situ with Lincoln Navigator – Test Configuration #9



Figure 1-10. In-Situ with Chevy Impala – Test Configuration #10



FCC ID: RS2SPRCI		FCC Pt. 15.239 / IC RSS-210 MEASUREMENT REPORT (CERTIFICATION)		Reviewed by: Quality Manager
Test Report S/N: 0809261430.RS2	Test Dates: October 1-14, 2008	EUT Type: Satellite Radio Receiver with FM Transmitter	Page 5 of 8	



Figure 1-11. In-Situ with Chevy Impala – Test Configuration #10



Figure 1-12. In-Situ with Chevy Impala – Test Configuration #10



FCC ID: RS2SPRCI		FCC Pt. 15.239 / IC RSS-210 MEASUREMENT REPORT (CERTIFICATION)		Reviewed by: Quality Manager
Test Report S/N: 0809261430.RS2	Test Dates: October 1-14, 2008	EUT Type: Satellite Radio Receiver with FM Transmitter	Page 6 of 8	



Figure 1-13. In-Situ with Pontiac G6 – Test Configuration #11



Figure 1-14. In-Situ with Pontiac G6 – Test Configuration #11





FCC ID: RS2SPRCI		FCC Pt. 15.239 / IC RSS-210 MEASUREMENT REPORT (CERTIFICATION)		Reviewed by: Quality Manager
Test Report S/N: 0809261430.RS2	Test Dates: October 1-14, 2008	EUT Type: Satellite Radio Receiver with FM Transmitter	Page 7 of 8	



Figure 1-15. In-Situ with Pontiac G6 – Test Configuration #11

FCC ID: RS2SPRCI		FCC Pt. 15.239 / IC RSS-210 MEASUREMENT REPORT (CERTIFICATION)		Reviewed by: Quality Manager
Test Report S/N: 0809261430.RS2	Test Dates: October 1-14, 2008	EUT Type: Satellite Radio Receiver with FM Transmitter		Page 8 of 8