Appendix B. Test Photos

1. Photographs of Conducted Emissions Test Configuration

TG585n



FRONT VIEW



Report No.: FR701818




SIDE VIEW

Report No.: FR701818

TG587n



FRONT VIEW






SIDE VIEW

2. Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz




FRONT VIEW



For radiated emissions 30MHz~1GHz



FRONT VIEW



For radiated emissions above 1GHz



FRONT VIEW

