

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1




Photo 2

Radiated Spurious Emission




Photo 1




Photo 2

Radiated Spurious Emission




Photo 3






Photo 4

Worst Case Position (Horizontal: X-axis/ Vertical:X-axis)


X-axis



Y-axis



Z-axis



Antenna Port Conducted




Photo 1

End of Report